

AD-A103 831 ENGINEER COMMAND (412TH) VICKSBURG MS
AIRFIELD DAMAGE REPAIR TECHNIQUES.(U)
JUL 81 D S HAWORTH, R S FLEMING, W S ANTHONY
UNCLASSIFIED R-81-11

F/G 13/2

NL

1 OF 1
AD
A103831


END
DATE
FILMED
10-81
DTIC

AD A103831

LEVEL

12

AIRFIELD DAMAGE REPAIR TECHNIQUES



DTIC
ELECTE
SEP 4 1981
H

Prepared by
412th Engineer Command
for
US Army Engineer Studies Center
July 1981

THE VIEWS PRESENTED IN THIS REPORT ARE
THOSE OF THE 412TH ENGINEER COMMAND
THEY DO NOT NECESSARILY REFLECT THE
OFFICIAL VIEWS OF THE UNITED STATES
ARMY

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution unlimited

DTIC FILE COPY

81 9 04 025

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A103 831	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Airfield Damage Repair Techniques		5. TYPE OF REPORT & PERIOD COVERED 9 Final
7. AUTHOR(s) LTC David S. Haworth, III MAJ Robert S. Fleming MAJ William S. Anthony Ms. G. Leslie Geiger		6. PERFORMING ORG. REPORT NUMBER R-81-11
9. PERFORMING ORGANIZATION NAME AND ADDRESS 412th Engineer Command Vicksburg, Mississippi		8. CONTRACT OR GRANT NUMBER(s) NA
11. CONTROLLING OFFICE NAME AND ADDRESS Engineer Studies Center 6500 Brookes Lane Washington, DC 20315		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS NA
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE July 1981
		13. NUMBER OF PAGES 50
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) NA		
18. SUPPLEMENTARY NOTES NA		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
Air Bases	XM-19 Mat	Regulated Set Concrete
Rapid Runway Repair	Class A Repair	Spall Repair
Collateral Damage	Class B Repair	Crater Repair
AM-2 Mat		Crushed Stone
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This monograph is one of a series prepared under the umbrella of the Engineer Studies Center's study: <u>US Army Engineer Assessment, Europe</u> . It describes the US Army engineer role in the repair of US Air Force air bases in Europe. Included is a description of the circumstances under which US Army engineers will make repairs to runways and taxiways, the current methods of repair, and what repairs will be made under Class A (permanent) and Class B (temporary) constraints. In summary, this monograph shows the preferred repair techniques in priority ranking for Class A, Class B, and spall repair and recommends areas for future study.		

DD FORM 1473
1 JAN 73

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

41

AIRFIELD DAMAGE REPAIR TECHNIQUES

Prepared by
412th Engineer Command
for
Engineer Studies Center

July 1981

Intelligence Cutoff Date:

September 1980

DISTRIBUTION LIST

No. of
Copies

Addressee

Department of Defense

1 Director, Defense Program Analysis and Evaluation/Land Forces
1 Director, Defense Research and Engineering
Joint Chiefs of Staff
1 Joint Staff (Plans and Policy)
1 Commander in Chief, European Command

Department of the Army

1 Deputy Under Secretary of the Army (OR)
1 Deputy Chief of Staff for Operations and Plans
1 Deputy Chief of Staff for Logistics
US Army Forces Command
1 Headquarters
1 First US Army
1 Fifth US Army
1 Sixth US Army
2 III Corps Staff Engineer
5 412th Engineer Command
US Army Europe
1 Office, Chief of Staff
2 Deputy Chief of Staff for Operations and Plans
2 Deputy Chief of Staff for Logistics
5 Deputy Chief of Staff, Engineer
V Corps
1 G-3
5 Staff Engineer
VII Corps
1 G-3
5 Staff Engineer
1 21st Support Command
US Army Training and Doctrine Command
1 Headquarters
1 Engineer
1 Logistics Center
1 Systems Analysis Activity
US Army Corps of Engineers
1 Assistant Chief of Engineers
1 Huntsville Division

Agencies

1 US Army Materiel Systems Analysis Agency
1 US Army Logistics Evaluation Agency
1 US Army Concepts Analysis Agency

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
and/or	
Dist. Special	
A	

No. of
Copies

Addressee

Schools and Centers

5	US Army Engineer School
1	Directorate of Combat Developments
20	US Army Training Center and Fort Leonard Wood
13	Defense Technical Information Center
	US Army Engineer Studies Center Library

Other

1	United States Air Force, Europe
---	---------------------------------

ACKNOWLEDGMENTS

All research, analysis, and initial report preparation were accomplished under the staff supervision of the Assistant Chief of Staff, Engineering, 412th Engineer Command, Vicksburg, Mississippi. Overall study guidance and assistance were provided by Mr. Dean E. Considine of the Engineer Studies Center. Principal writers of this report were MAJ Robert S. Fleming and MAJ William S. Anthony, 412th Engineer Command. The Project Manager was LTC David S. Haworth III, 412th Engineer Command. Important contributions to the study were made by Dr. George Hammitt of the US Army Waterways Experiment Station. Other resource personnel making key contributions to the study include Mr. Bob Van Orman of Tyndall Air Force Base, Florida; LTC Ted Stroup and his staff at the 293d Engineer Battalion, Baumholder, Federal Republic of Germany; the 18th Engineer Brigade commanded by COL James Van Loben Sels; and LTC Chuck Dominy and MAJ Bill Traubel of the Plans Branch, Deputy Chief of Staff, Engineering, Headquarters, US Army, Europe. The final text and revisions were prepared by Ms. G. Leslie Geiger of the Engineer Studies Center.

This study was prepared for publication by Mrs. Estelle C. Coleman, Miss Donna L. Jones, and Miss Anne E. Purcell under the direction of Ms. Doreen A. Myers. The editor was Mrs. Ruby B. Sherwood. Graphics support was provided by Mr. Abell A. Norris III under the supervision of Mr. Christopher Y. K. Lew.

CONTENTS

<u>Section</u>		<u>Page</u>
	DISTRIBUTION LIST	iii
	ACKNOWLEDGMENTS	v
	CONTENTS	vii
	ABSTRACT	ix
	LIST OF ABBREVIATIONS	xi
I	INTRODUCTION	
	Purpose	1
	Scope	1
	Study Methodology	1
	Assumptions	2
	General	3
II	ALTERNATIVE REPAIR TECHNIQUES	
	Current Methods of Repair	6
	Repair Conditions and Criteria	6
	Class B Repairs	9
	Class A Repairs	17
III	CONCLUSIONS	
	Class B Repair Techniques	26
	Class A Repair Techniques	27
	Small Crater Repair Techniques	28
	Spall Repair Techniques	28
IV	RECOMMENDATIONS	
	Summary	29
	Future Studies	30
 <u>Figure</u>		
1	Specifications for Representative Tactical and Cargo Aircraft	9
2	Minimum Thicknesses for Class B Crushed Stone Repairs	13
3	Minimum Thicknesses for Class A Repairs	18
4	Recommended Repair Techniques in Priority Ranking	29
 ANNEX A--TYPICAL CRATER		
		A-1
 ANNEX B--CRUSHED STONE REPAIR		
		B-1
 ANNEX C--GRADATION CURVES FOR CRUSHED STONE		
		C-1
 ANNEX D--BIBLIOGRAPHY		
		D-1

ABSTRACT

This monograph is one of a series prepared under the umbrella of the Engineer Studies Center's study: US Army Engineer Assessment, Europe. It describes the US Army engineer role in the repair of US Air Force air bases in Europe. Included is a description of the circumstances under which US Army engineers will make repairs to runways and taxiways, the current methods of repair, and what repairs will be made under Class A (permanent) and Class B (temporary) constraints. In summary, this monograph shows the preferred repair techniques in priority ranking for Class A, Class B, and spall repair and recommends areas for future study.

LIST OF ABBREVIATIONS

ADR.....airfield damage repair
AFB.....Air Force Base
AFR.....Air Force Regulation
AFSC.....Air Force Systems Command
APOD.....aerial port of debarkation

CBR.....California bearing ratio

DAF.....Department of the Air Force
DCSENGR.....Deputy Chief of Staff for Engineering

ENGCOR.....Engineer Command
EOD.....explosive ordnance disposal
ESC.....Engineer Studies Center

FOD.....foreign object damage
FRG.....Federal Republic of Germany

HN.....host nation

JCCRS.....Joint Contingency Construction Requirements Study
JCS.....Joint Chiefs of Staff

MOS.....minimum operating surface

NATO.....North Atlantic Treaty Organization

OCORUS.....outside continental United States

POL.....petroleum, oils, and lubricants
psi.....pounds per square inch

RRR.....rapid runway repair

STANAG.....Standardization Agreement

USAF.....United States Air Force
USAFE.....United States Air Force Europe
USAREUR.....United States Army Europe

UXO.....unexploded ordnance

WES.....United States Army Corps of Engineers Waterways Experiment
Station
WP.....Warsaw Pact

AIRFIELD DAMAGE REPAIR TECHNIQUES

I. INTRODUCTION

1. Purpose. This monograph addresses the US Army engineer role in the repair (or in support of the repair) of USAF air bases in Europe. It discusses the type of war damage repair that US Army engineer units will probably perform at USAF air bases during a NATO contingency in Europe, and it suggests the most efficient and effective techniques to use in completing these repairs.

2. Scope. This study considers two basic types of war damage to USAF air bases in the rear combat zone in Europe--runway and collateral.^{1/} It deals primarily with runway and taxiway repairs, since this type repair is envisioned as the most urgent during the initial days of a war insofar as the Army engineers are concerned. This study looks closely at the technical aspects of ADR, including a discussion of the types of repair and an evaluation of alternative methods.

3. Study Methodology. The study was initiated during September 1979 with discussions between ESC and the 412th ENGCOR to define the scope and purpose. ESC provided additional study guidance to the 412th ENGCOR in January 1980. A literature search was conducted to locate and review the various studies of crater repair that have been prepared in recent years. Annex D is a partial bibliography for the literature review. Early in the study, interviews were held with personnel at the USAF Engineering and

^{1/} Runway damage is by far the most important and includes large craters, small craters, spalls, and surface damage on the runway and taxiways. Collateral damage includes war damage to control towers, runway lighting, POL facilities, roadways, aircraft shelters, arrester gear, ammunition and weapon storage facilities, avionics, weapons maintenance facilities, communication systems, electrical distribution systems, and buildings.

Services Center, Tyndall AFB, Florida, and at the US Army Corps of Engineers Waterways Experiment Station, Vicksburg, Mississippi. These interviews provided information on both Air Force and Army research in runway repair techniques and added to the literature available to the study team. An OCONUS trip by the study team was made in January 1980. During this trip, the team spent time with the Plans Branch, DCSSENGR, Headquarters, USAREUR, Heidelberg, FRG; the 293d Engineer Battalion, Baumholder, FRG; and USAFE engineering personnel, Ramstein AFB, FRG. The 293d Engineer Battalion has considerable field experience with various damage repair techniques. That unit has field tested some of the techniques proposed by WES. The 293d also has considerable data on repair techniques used by other NATO countries. That information was made available to the study team and is briefly described in this report.

4. Assumptions. The study was based on the following assumptions.

- a. The Army will continue to have a mission to support the USAF in ADR, to include emergency repairs and follow-on restoration.
- b. Due to the level of damages and limited USAFE and HN capabilities, the US Army engineers will have to assume emergency repair missions on airfield runway and taxiway surfaces.
- c. Tactical aircraft require an MOS of 50 feet by 5,000 feet and a 25-foot wide meandering taxiway.
- d. Nontactical and civilian-type planes require an MOS of 75 feet by 7,500 feet and a 25-foot wide meandering taxiway.
- e. Reconnaissance, damage assessment, and selection of the minimum repair area for the MOS will be accomplished within a very short time frame by the USAF.
- f. EOD, a critical part of the repair effort, will be accomplished by nonengineer assets.

g. The equipment and materials necessary to make the rapid repairs will be procured and made available at the air bases.

5. General.

a. Background literature.

(1) A review of current literature suggests that very real problems exist within the plans and capabilities of the engineer resources allocated for war damage repair at USAF air bases. The recent JCS Joint Contingency Construction Requirements Studies II (JCCRS II) identified the level of damage anticipated at USAF air bases in Europe. The JCCRS II study also surfaced a number of questions related to war damage repair. For example, what kinds and quantities of war damage repairs require immediate attention, which can be accomplished over a longer period of time, and which of those should be done by US Army engineer units?

(2) DOD Directive 1315.6^{2/} outlines the responsibilities for war damage repair of USAF air bases. US Army engineers are responsible for all semi-permanent repairs and restoration of war-damaged facilities at USAF air bases. Also, should USAF requirements for emergency repair and force beddown exceed the capability of organic USAF engineers, the US Army engineers have the added responsibility of assisting the USAF in performing these tasks.

(3) The current threat analysis as presented in a draft of STANAG 2929^{3/} and specific study guidance from ESC (dated January 1979)^{4/} were used as the basic criteria in evaluating the required ADR.

2/ DOD Dir 1315.6, Responsibilities for Military Troop Construction Support of the Department of the Air Force Overseas. (For complete bibliographic information on this document, and those following, see Annex D.)

3/ NATO, NATO STANAG 2929--Airfield Damage Repair.

4/ DA, USACE, OCE, ESC, Study Guidance for Air Force Support Study.

b. Essential ADR mission elements.

- (1) Reconnaissance/damage assessment.
- (2) EOD.
- (3) RRR.^{5/}
- (4) Collateral damage repair to the following.
 - (a) Operational facilities.
 - (b) Communication systems.
 - (c) Ammunition storage facilities.
 - (d) Essential maintenance facilities.
 - (e) Fuel storage and distribution.
 - (f) Utilities.
 - (g) Access routes (on and off base).

(5) Semi-permanent/permanent runway repair and restoration.

c. UXO. UXO disposal at USAF air bases poses a significant problem.

Critical air bases are assigned only a limited number of USAF EOD personnel. If there are numerous UXOs in the operating area to be repaired, the USAFE EOD personnel capability will be greatly exceeded. However, this report does not address EOD requirements, although this is recognized as a major potential problem area. It should be noted that the engineer units supporting an air base do not have the organic capability to handle EOD requirements.

d. Collateral damage. In addition to repair of paved surfaces as discussed above, the Army is also responsible for assisting the USAF in repairing critical air base support facilities. The USAF Prime Beef teams will perform the temporary emergency repairs and the Army engineers will perform the semi-permanent and permanent repairs. The methods of repair for

^{5/} RRR is the primary focus of this report.

collateral damages are basically the same as normal engineer construction techniques that are within the capability of the combat heavy battalion. Discussion of these missions and methods of repair is not included as part of this study.

II. ALTERNATIVE REPAIR TECHNIQUES

6. Current Methods of Repair.

a. The current USAF method for emergency repair of craters uses AM-2 aluminum matting placed after the crater has been filled with ejecta and 12 inches of select fill. Computer simulations conducted by the USAF^{6/} have predicted roughness problems with the AM-2 mat system when used by tactical aircraft. The AM-2 mat system is a temporary repair and can withstand only limited use.

b. The US Army engineers' only established method for temporary repair of craters is with the use of the AM-2 mat. However, the Army has no AM-2 mat in the supply system. The Army does have the XM-19 mat authorized for use; however, its availability is limited and many problems exist in using this mat for crater patches.

c. The Geotechnical Laboratory of WES is researching certain techniques for temporary repairs and some of these have been field tested by the 293d Engineer Battalion at Baumholder, FRG. Planning efforts of US Army engineers have been directed toward semi-permanent or permanent repair methods such as asphalt or concrete. These methods may require more time and manpower than will be available in a post-attack environment, especially in view of the potential for repeated attacks. These methods also depend on the availability of specialized materials.

7. Repair Conditions and Criteria.

a. General.

(1) Under the current threat analysis of WP forces, extensive damage to air base facilities is expected, and the damage can be repetitive.

^{6/} DAF, AFCS, AF Weapons Lab, Computer Program for the Prediction of Aircraft Response to Runway Roughness.

This study subdivides the damage to runways, taxiways, and hardstands into three categories: large craters whose depths exceed 3 feet with a diameter of about 60 feet; small craters with depths less than 3 feet and a diameter of 20 feet; and spalls. Spalls are small craters that do not completely penetrate the pavement. Collateral damages that may be associated with an attack include damages to POL facilities, roadways leading to and from the POL facilities, electrical and lighting systems, and buildings.

(2) The first priority of repair at a tactical air base is to restore a minimum 50-foot by 5,000-foot tactical aircraft landing strip within 4 hours. Follow-on tasks are to provide an additional 50-foot by 5,000-foot tactical aircraft strip and to upgrade the initial emergency repair to a more permanent standard. At APODs, the initial priority is to restore a minimum 75-foot by 7,500-foot landing strip for reception of nontactical and civilian aircraft. Upgrading of the initial emergency MOS should be accomplished as soon as possible. The initial 4-hour time frame includes the necessary initial UXO disposal and times needed to complete small and large crater repairs.

(3) Class A and Class B are the two basic repair categories used in this study. Each of these methods is considered separately for USAFE tactical air bases and the civilian APODs that handle nontactical aircraft. Class B repairs are those rapid, expedient repairs that provide a temporary surface able to withstand at least 24 hours at NATO maximum rates of sortie generation for tactical aircraft. These types of repair should be upgraded as soon as time and scheduling permit. Class A repairs are those rapid repairs that are semi-permanent or permanent in nature and could be expected to endure repeated loadings over a long period of time.

b. Runway conditions. The typical runways and taxiways encountered in Europe will consist of asphaltic concrete overlays in thicknesses from 2 to 8 inches, portland cement concrete pavement in thicknesses from 4 1/2 to 12 inches, and base course materials. Base course materials are select materials intended to serve as granular, high-strength layers from 9 inches to as much as 66 inches. The subgrades on which these pavements are placed vary in classification and strength. Gravels, sands, clays, and combinations of these materials can be found in most subgrades. WES research documents indicate that 5 to 25 percent of airfield pavement surface area will be damaged by large and small bombs and other ordnance such as cannon fire. The probable volume of ejecta associated with this type damage could be 6,000 cubic yards, or an average of up to 8 inches deep over the entire runway and taxiway area. It is reasonable to assume that these attacks will be repeated until Allied air superiority is achieved. UXOs, as well as follow-up attacks, will make the initial repair efforts especially hazardous. The possibility of performing these repairs in a chemically toxic environment is also very real.

c. Wheel loading. As discussed earlier, there are different MOS requirements for tactical and nontactical aircraft. For purposes of this study, the wheel loadings for various aircraft are subdivided into two basic categories--tactical and nontactical. (Figure 1 shows some specifications for one representative-type tactical and one representative-type nontactical aircraft.) The F4C-type aircraft is referred to as the typical tactical aircraft. The nontactical or cargo-type aircraft include the C5A, C141, C130, and civilian-type aircraft such as the DC-10, 747, and L1011. The C141A is considered the typical nontactical aircraft, since its wheel configuration and loadings are considered the most critical for pavement loading.

SPECIFICATIONS FOR REPRESENTATIVE TACTICAL AND CARGO AIRCRAFT

Aircraft	Max Takeoff Weights (Kips)	Design Loads (Kips) ^{a/}	Contact Area (Sq In)	Tire Pressure (psi)	Main Gear Load (Kips) ^{b/}
F4C (Tactical)	59.1	26.0	102	255	26.0
C141A (Nontactical)	316.6	149.5	208	180	149.5

SOURCE: DA and DAF, jointly, TMS-330 and AFM 86-3, Planning and Design of Roads, Airbases, and Heliports in the Theater of Operations.

^{a/} Design loads for each wheel of the main landing gear.

^{b/} For each of two wheels.

Figure 1

d. Weather effects. In addition to time constraints and the type of aircraft (i.e., tactical or nontactical) that will use the runway, weather is also very critical in crater repair. It is critical because it is almost impossible to use ejecta from the crater as fill material during inclement weather such as rain or sleet.

8. Class B Repairs.

a. General. This paragraph discusses the organization and techniques used by the USAF for emergency runway repair using the AM-2 mat and the current USAF research efforts on other repair techniques. It briefly discusses techniques being used by other NATO countries and also covers the various methods investigated for RRR that may be suitable for use by Army engineers. Suitable methods include crushed stone, mat, and regulated set concrete.

b. Methods for USAF.

(1) The USAF has the responsibility to make emergency repairs to the extent necessary to accomplish its air mission. These repairs include a minimum 50-foot by 5,000-foot runway and a 25-foot wide meandering taxiway. The USAF intends to perform this mission with contingency force Prime Beef Teams CF-1 and CF-2, which form a 91-man RRR force manned by 5 officers and 86 pavement maintenance specialists and equipment operators. During peacetime these teams work as part of the Base Civil Engineering Squadron and perform maintenance for pavement, heating, plumbing, refrigeration, and buildings. The composition and specialties of the individuals included in these teams are listed in Chapter 2, AFR 93-3^{7/} The AM-2 mat repair method is the current method of RRR used by the USAF. It is described in detail in AFR 93-2^{8/} and is summarized below.

- (a) Ejecta greater than 12 inches are pushed off the runway.
- (b) The "heaved lip" in the pavement around the crater is removed.
- (c) The crater is filled with ejecta to within 12 inches of the runway surface and is lightly compacted with a dozer.
- (d) At least 12 inches of select fill is then added and compacted lightly with a dozer to achieve a CBR of at least 4.
- (e) Sufficient AM-2 mat with edge ramps is assembled, pulled over the filled crater, and secured to the runway.

^{7/} DAF, HQ, AFR 93-3, Air Force Civil Engineer Prime Beef Program.

^{8/} DAF, HQ, AFR 93-2, Disaster Preparedness and Base Recovery Planning.

(2) The 91-man Prime Beef team is trained to repair three large craters per 4-hour period. The AM-2 mat is prepackaged in kits that contain all ancillary items and tools necessary to facilitate their use. The number of AM-2 patch kits available to the team controls the total number of achievable crater repairs.

(3) The USAF research facility at Tyndall AFB, Florida, is working to develop additional ways to repair damaged pavement. The current USAF method described above may prove to be outmoded in light of the current threat analysis. AM-2 does not make an efficient repair material for airfields extensively damaged with small craters (less than 20 feet in diameter). The USAF is also concerned that AM-2 mat repair may cause structural damage to aircraft because the 1 1/2-inch thick mat lies on top of the pavement surface, thereby creating a bump. According to the Air Force Engineering and Services Center at Tyndall AFB, one of the most promising systems being studied is the crushed limestone repair method^{9/} This crushed-limestone method involves refilling the crater with ejecta topped with a single lift of well-graded, high-quality crushed limestone 24 inches thick. It is then compacted only from the surface with 32 passes of a 10-ton vibratory roller. USAF tests have shown that pavement repaired by this method can successfully carry F-4 and C141A aircraft wheel loads. Further tests are underway to minimize the lift thickness, number of compactor passes, and to develop an FOD cover. (FOD is caused by the ingestion of foreign objects into jet engines and by the foreign objects causing external damage to the aircraft.) There are two factors which bear unfavorably on using this method of repair.

^{9/} This repair method is based on the prior provision of an adequate supply of crushed stone stockpiled adjacent to the runway. The analysis considers a typical crater as shown in Annex A.

(a) The USAF has only a very limited number of 10-ton vibratory compactors.

(b) USAF operations personnel are not currently being trained in the crushed stone method of repair.

c. Methods for Army engineers--tactical aircraft.

(1) For tactical aircraft, the AM-2 mat method and the crushed stone method are available for Class B repairs. Army documentation describes the crushed stone method somewhat differently from that described above for the USAF. The Army procedure^{10/} is described below.

(a) Separate the ejecta; remove all ejecta greater than 12 inches and push it to the side of the runway.

(b) Fill the crater to within the required thickness with ejecta smaller than 12 inches in diameter and compact lightly with a dozer and vibrator.

(c) Place crushed stone in a concave lift procedure with 12-inch lift thickness whereby each 12-inch lift terminates at the surface and facilitates the entrance and exit of construction equipment into the crater.

(d) Compact each of the lower lifts with vibratory rollers to 95-percent CE55 modified density. The top 12-inch lift is compacted to 100 percent or greater of CE55.

(e) Overbuild the final lift by 2 to 3 inches and compact with the heaviest rubber-tired roller available (eight roller passes should suffice).

^{10/} DA, USACE, OCE, WES, Airfield Damage Repair.

(f) Blade off and compact again with four passes of the 50-ton roller. If no 50-ton roller is available, the heaviest available roller should be used.

(2) The required thickness of crushed stone is a function of the type of foundation. For a weak clay material, 24 inches are required; for a high clay granular mixture, 16 inches are required; and for a high clay granular material with low fines, 12 inches will suffice. In most cases, if there is a question as to the kind of foundation, 24 inches of crushed stone should be used. Figure 2 gives the minimum required thickness for various foundations for tactical and nontactical aircraft.

MINIMUM THICKNESSES FOR
CLASS B CRUSHED STONE REPAIRS

Foundation Strength	Aircraft	Crushed Stone ^{a/} (inches)
Weak clay material	F4	24
	C141 and F4	38
Medium clay, granular mixture	F4	16
	C141 and F4	21
High clay, granular, low fines	F4	12
	C141 and F4	15

^{a/} See Annex C for gradation of crushed stone.

Figure 2

(3) The crushed stone method of rapid repair requires changes when inclement weather exists. Water in the crater can be pumped out prior to the repair. However, if heavy rains occur during the repair process, the

ejecta will become unusable as fill material in the crater. If the ejecta turns to mud, no bearing can be obtained with the crushed stone. One alternative construction method in inclement weather is to pump the water from the crater and fill the entire crater with the crushed stone. Another alternative is to line the crater with an impervious membrane, fill the lower portion of the crater with large rocks (3 to 5 inches in diameter), and then fill the remainder with compacted crushed stone. All ejecta must be removed from the runway.

(4) The crushed stone surface will require an asphalt tack coat with a sand blotter to eliminate FOD. The surfacing layer can be placed with an emulsified asphalt sprayed with a distributor spray bar or a portable sprayer at the rate of 0.1 to 0.3 gallons per square yard. The sand blotter can be spread by personnel using hand tools.

(5) This type of repair will last for an extended period of time if the repaired craters are observed after use and necessary repairs in the form of additional stone and compaction are made when needed. This repair technique could be expected, with minor maintenance, to last for several days or until the combat situation would permit semi-permanent or permanent repairs. Annex B shows a cross-section sketch of a crushed stone repair technique with tack coat.

(6) The AM-2 mat could be used by the Army engineers if it were available to them. Presently, however, there are only minimal stocks in the Army Supply System. The study team considered the use of XM-19 mat that is in the Army Supply System. However, there are no end ramps available for the XM-19 mat, and tactical aircraft cannot handle the abrupt change in runway elevation that the lack of end ramps would cause. Also, there is presently no

tiedown system designed for the XM-19 mat. Therefore, for practical consideration, XM-19 mat is not a reasonable option to Army engineers for rapid crater repair for tactical aircraft.

(7) Regulated set concrete has been tested as a rapid repair technique and has proven difficult to use because of the unpredictable setting time, the skill requirements for the personnel placing the concrete, and the availability of materials and specialized equipment at the time and place needed. Asphalt and concrete caps take longer to construct and are discussed later in paragraph 9 of this section under Class A semi-permanent and permanent repairs for tactical and nontactical aircraft.

d. Methods for Army engineers--nontactical aircraft.

(1) The crushed stone method of repair as described above is suitable as a Class B repair technique for nontactical aircraft at APODs. The thickness of stone required varies with the foundation strength and should be as shown in Figure 2. Requirements for thicknesses of stone are greater for nontactical aircraft and range from 15 to 38 inches. Compaction should be in 12-inch lifts as described in paragraph 8c for tactical aircraft. When foundation conditions are unknown, 38 inches of crushed stone should be used. If rain makes use of ejecta impossible, the entire crater could be filled with stone. Use of an impermeable membrane liner should also be considered.

(2) Mat provides a second option for nontactical airfields. The AM-2 mat would not likely be available to the Army. However, the XM-19 mat in the Army Supply System can be used since cargo-type aircraft are not affected significantly by the 1 1/2-inch bumps produced on the runway and, hence, the lack of end ramps is not a problem. Based on discussions with design engineers at Douglas Aircraft Company, civilian aircraft such as the DC-10, Boeing

747, and L1011 would not be adversely affected by the uneven surface except for possible tire damage. The repair procedure would be very similar to that the USAF uses with the AM-2 mat. The bridging characteristics of the XM-19 mat are as good as the AM-2. Use of the XM-19 mat as a patch is not discussed in the literature, but WES research personnel indicate that it would be a totally acceptable repair technique. A problem with lateral stability of the mat will occur if the pilot applies the brakes while crossing the mat. However, the same problem exists with the AM-2 mat because the grouted anchor system will not hold under the braking force of a C141 or other cargo-type aircraft.

e. Small crater repair. The techniques for repairing small craters are the same as for large craters. Compaction is more difficult in a small crater due to the large size of the equipment being used. It is estimated that a small crater repair will require 75-80 percent of the time and effort required for a large crater repair.

f. Spall repair. Spalls or small craters that do not completely penetrate the pavement will be numerous throughout the area of runway/taxiway being repaired. The repair of spalls does not lend itself to a Class B repair to be upgraded later. Spall repairs will be discussed in the Class A repair portion of this report since the repair method is the same for Class A and Class B.

g. ADR repair in other NATO countries.

(1) FRG. Primary responsibility for ADR belongs to the Luftwaffe Engineers and secondly to the Territorial Army. The FRG uses AM-2 mat patches and a rapid or emergency repair technique similar to that of the USAF.

(2) Great Britain. The primary responsibility for ADR belongs to the British Royal Engineers. Their emergency repair technique involves filling the crater with rock and using a mat patch. The mat, a Class 60 trackway in panels that are fitted together, is stored in rolls. It differs from the AM-2 but has the same capabilities. Select fill material is currently stockpiled along the runway. The British also use a self-propelled pavement breaker to assist in crater preparation.

(3) France. The French repair method includes trimming the crater edges to form a rectangular area. The crater is filled with rock to the level of the surface. A pierced steel mat patch is pulled into place and sunk flush with the adjacent pavement by using a vibratory roller. Cold bituminous pavement is used to join the mat to the pavement.

9. Class A Repairs.

a. General. This paragraph discusses semi-permanent and permanent repair techniques. These repairs are not constrained by the rigid time requirements under emergency or rapid repairs. The USAF has no Class A repair mission, since these responsibilities are assigned to the Army engineers. The techniques available include the use of concrete, asphalt, and the crushed stone used for Class B repairs. It is assumed that as soon as the combat situation permits, the emergency repairs and rapid repairs would be upgraded to Class A. The Class A methods presented differ for tactical and nontactical airfields only in thickness of surface and bearing (see Figure 3). Therefore, tactical and nontactical airfields are not separated for presentation in this section. The type of Class A repair performed will be a function of the construction materials available at the air base. The proven Class A repairs that are available are the crushed stone method, the flexible

pavement method, and the rigid pavement method. The minimum requirements for those repairs are also a function of the following.

- (1) The foundation material strength.
- (2) The type of aircraft. (Figure 3 considers the critical wheel loads for tactical and nontactical aircraft only.)
- (3) The type of construction material available for repair as indicated in Figure 3 (which includes the crushed stone requirements from Figure 2).

MINIMUM THICKNESSES FOR CLASS A REPAIRS

Strength	Aircraft	Crushed Stone (Inches)	Flexible Pavement (Inches)	Concrete Pavement ^{a/} (Inches)
Weak clay material	F4	24	28	14
	C-141 and F4	38	44	15
Medium clay, granular mixture	F4	16	18	13
	C-141 and F4	21	24	14
High clay, granular, low fines	F4	12	14	12
	C-141 and F4	15	18	12

^{a/} Requires 24 inches of crushed stone base.

Figure 3

b. Upgrading USAF emergency repairs. The AM-2 mat patch placed by the USAF will be removed for reuse, and Army engineers will make semi-permanent or permanent repairs. Since the mat patch requires very little compactive effort, the top portion of the emergency crater fill will have to be removed and replaced with a well-compacted base to facilitate the permanent

repair. The same would hold true for a patch if XM-19 or any other type mat were used.

c. Crushed stone method. The crushed stone method of repair was discussed earlier as the most logical Class B repair technique for use by Army engineers. It is basically a temporary-type repair. However, with some maintenance, it can last for an extended period of time. There are some techniques which can be used to make the crushed stone repair more durable.

(1) A well-graded, well-compacted, high-quality crushed stone repair does not require a surfacing layer except for prevention of FOD. Preventing FOD for Class B repairs can be accomplished with an emulsified asphalt sprayed at the rate of 0.1 to 0.3 gallons per square yard and sealed with a uniform sand blotter course.

(2) Better surfaces could be provided to reduce the repairs needed. For example, the top 6 inches of crushed stone can be blade-mixed with 10 percent or more type III PCC or BN 550 high-early strength cement, wetted and compacted for the surfacing layer. If available, high-quality hot-mix asphalt may be placed to a 4-inch minimum depth on top of the crushed stone. A silikal cap placed over the crushed stone is another method that has been tested and will work, but it is probably better suited to small craters. Silikal is an acrylic concrete made in the FRG and is discussed in subparagraph 9h of this section. A uniformly graded aggregate is needed for the top 30 millimeters when using silikal.

(3) When using the crushed stone repair method in inclement weather, additional crushed stone is used instead of ejecta and some form of impermeable membrane such as filter fabric should be used in the bottom of the crater to keep the wet foundation separated from the free-draining crushed

stone. This is a standard procedure used in building roads on soft ground or permafrost areas.

d. Rigid pavement method.

(1) The rigid pavement solution is well documented in research publications. Crater ejecta are removed with a bucket loader and the heaved sections of pavement are pushed out of the crater with a dozer. The crater is backfilled with ejecta and compacted with a dozer or vibrator to achieve a minimum of 85 percent of CE 55 modified density. This is very difficult to achieve, especially in small craters where compaction equipment cannot be used effectively. Therefore, washed gravel or crushed stone can be used to provide a 24-inch base for the concrete cap with considerably less compactive effort. A prefabricated screed pedestal is placed in the center of the crater for use in screeding and finishing the concrete. There are several pedestal designs, but the type recommended, a disc 4 feet in diameter and 1 foot thick, has steel dowel bars. This type has no corners for stress concentrations and has steel dowels for load transfer. A 2-inch by 6-inch deep hole is required in the center for the screed pin. The rigid pavement cap can consist of either high-early strength concrete or type I PCC. Each of these materials has an age versus strength relationship that is influenced by the water-cement ratio, type cement, temperature, humidity, and percent accelerator used. The specific concrete mix that is used will determine the curing time required before traffic is allowed. The concrete must have obtained a 1,500-psi compressive strength before it is subjected to traffic. A time versus strength gain curve must be obtained for any particular rigid pavement concrete mix. About 160 hours of curing time is required before traffic can be

allowed on a rigid pavement patch using BN 250 concrete without accelerators. The BN 550 concrete mix which contains 2 to 4 percent (by cement weight) concrete liquifier (BVF) and 8 percent (by cement weight) accelerator (B-3) will allow traffic in 8 hours. Regulated-set concrete which would allow traffic in 4 hours has been tried, but based on conversations with field people,^{11/} it is very difficult to use with engineer troops. It would require highly trained specialists and additional specialized equipment that is quite expensive.

(2) If a rigid pavement repair is being used to upgrade an AM-2 mat patch, the mat can be pulled aside and then pulled back over the partially cured concrete to allow for some traffic during curing of the rigid pavement patch.

(3) It should be emphasized that a high-volume source of dependable concrete and necessary delivery vehicles must be available before this repair technique can be undertaken.

(4) Rigid pavement may also be used to upgrade a crushed stone repair (described earlier). This repair technique requires that some of the crushed stone fill be removed before placing the desired thickness of concrete. This could result in as little as 12 inches of crushed stone remaining. It is essential that the remaining stone be recompact to its full load-bearing capacity. The top layer of stone should be removed using either a road grader or a dozer with scarifier teeth. The excavated stone should be stockpiled for future use in other areas. In small craters, jackhammers and hand tools may be needed to loosen and remove the stone. Placing the concrete cap requires the same procedures and equipment as described earlier. The

^{11/} 293d Engineer Battalion, Baumholder, FRG.

runway should not be used until the concrete has developed at least 1,500 psi compressive strength.

(5) Load transfer mechanisms must be installed between the existing runway and the pavement cap.

(6) A self-propelled pavement breaker (such as the Arrow Model D500) is essential to straighten the crater edges, minimize difficulties with obtaining load transfer, and simplify placement procedures.

e. Flexible pavement method. A high-quality hot-mix asphalt can be used as a semi-permanent or permanent flexible pavement repair. Figure 3 shows the required thicknesses which range from 14 to 44 inches. Placing asphalt in these thicknesses with proper compaction in a crater would be difficult, slow, and time consuming. For this type use, a volume production plant must be available in the general area. Delivery could be made using 20-ton dump trucks now in the Army inventory. Heated beds will be required for long hauls. The best use of hot-mix asphalt will be in upgrading a crushed stone repair. As discussed under the crushed stone Class A repair, this could be done with a 4-inch asphalt cap placed during the initial crater repair or during upgrading of a crushed stone repair. The upgrading would include using the scarifier teeth on a dozer or a road grader to break up the stone to about a 6-inch depth with about 4 inches of the stone removed. Compaction of the remaining stone is essential for load transfer and should be accomplished by roller and tamper before placement of asphalt. Care should be taken to ensure that damaged surfacing material around the edge of the crater is removed. The crater edges should be trimmed to provide a clean vertical edge using a self-propelled pavement breaker, jackhammers, air compressor, and hand tools. Irregular shapes will increase the asphalt placement difficulties as a result

of physical constraints of the paving machine, and thus increase the placement time to an unacceptable level. The area must be cleared of loose material on the base, including dust and dirt which will interfere with bonding of the prime coat to be applied to the base material. General asphalt procedures are given in TM 5-337.^{12/} The standard requirement for a 48-hour curing time for the prime coat may require either elimination of the prime coat or using an RC cutback with faster curing time. The 48-hour delay is not considered acceptable during combat conditions. The prime coat may be eliminated in extremely cold weather. The paving operation includes placing, spreading, and rolling to grade and proper density.

f. Repair techniques in other NATO countries.

(1) FRG. Use of concrete is the preferred method of permanent repair; however, the Germans are researching vacuum drying of concrete. They have some stock of precast paving blocks to place as a surface material.

(2) Great Britain. Concrete is the preferred method of repair; however, the British are researching a method of deep dynamic compaction. This is done using a large weight dropped from about 10 feet. The method is currently used on civilian airfields for foundation improvement and could have some use to Army engineers in upgrading craters repaired by USAF emergency methods.

(3) Netherlands. The Dutch are investigating the use of blast furnace slag as a fill material.

g. Small crater repair. Small craters present several problems in making Class A repairs. Most engineer equipment is too large to be used effectively in the repair, and there has been little study and field testing

^{12/} DA, HQ, TM 5-337, Paving and Surfacing Operations.

of repair techniques for small craters. Most of the study and research have involved the large or NATO standard crater. As a result of their training efforts, the 293d Engineer Battalion discovered that there was no definite technique developed for small crater repair and that there appears to be little difference between the times required for repair of small and large craters. The methods of repair for small craters are essentially those that are discussed for large craters--crushed stone method, the rigid pavement method, and the flexible pavement method. The steps in performing these repairs are basically the same as for large craters except smaller equipment is required. The 293d Engineer Battalion found that the 2 1/2-cubic yard loader and the towed airmobile vibratory compactor were about the right size. For the rigid pavement solution, a screed pedestal is not required; but more field testing is needed to fully develop a method for using the screed beam on the smaller craters.

h. Spall repair. One method for repairing spalls that was developed by the British Royal Engineers is placing a 3/4-inch steel plate over the cavity and bolting it in place. A variation of this method developed by the 293d Engineer Battalion involves filling the cavity with concrete and placing the plate over it to protect the fresh concrete. This allows reuse of the plate after the concrete is set. Hot-mix or cold-mix asphalt can also be used. Another method is to fill the cavity with silikal. Silikal comes in separate liquid and powdered components that are mixed at the job site. It sets rapidly and can be used as a wearing surface 1 hour after application. It produces a permanent repair similar to concrete, but with far less curing time. Silikal fumes are quite strong and could require the use of masks and gloves. It does not set well in wet conditions. These factors, plus the

requirement for hand placement, limit its potential for large and small craters. Spalls in wet areas could be covered with a canvas and dried with air from an air compressor before the silikal is applied.

III. CONCLUSIONS

0. Class B Repair Techniques.

a. Tactical aircraft. Based on the present day "state-of-the-art" and considering material availability, the crushed stone method with an FOD cover is the best Class B repair method available to US Army engineers.^{13/} The AM-2 mat method is an acceptable repair procedure, but the USAF owns nearly all of the AM-2 mat kits and has dedicated them to USAF engineers. Variations of the crushed stone repair method exist since the amount of crushed stone required is a function of the type aircraft and the foundation material. The procedure of placing the full 24 inches and compacting from the top down with 32 passes of a 10-ton or larger vibratory roller may be the least complicated and most rapid method for making an emergency Class B repair. During inclement weather, the best method is to use a membrane or filter fabric to provide a separation between the foundation and the crushed stone and to fill the crater completely with crushed stone. The membrane is not required, but would be helpful. The Army needs to purchase half panels, end ramps, and an anchor system for the XM-19 mat so that it can be used as a mat patch for tactical aircraft. Making these items available would provide a second Class B repair method for Army engineer units.

b. Nontactical (APOD). The crushed stone technique is the best method now available for Class B repair for nontactical aircraft. The required thicknesses are shown in Figure 2. A second (but less satisfactory) method that can be used at APODs for nontactical aircraft is an XM-19 mat patch that could be anchored to the runway with grouted anchors, drilled

^{13/} One important fact that should be understood about the crushed stone method is that the material must be a high-quality, well-graded stone that meets the requirements of the gradation band shown in Annex C.

through the mat, and bolted down with oversize washers. XM-19 patch repair could be used on APODs without half panels and end ramps. However, use of this method would preclude use of the strip for tactical aircraft.

11. Class A Repair Techniques.

a. The Class A repair method that the Army engineer unit will use depends on the weather, the availability of materials and delivery systems (i.e., concrete and asphalt production and haul capability), and on whether the repair is an upgrade or a new repair. If it can be assumed that there are no constraints as to materials, costs, and time, the preferred techniques would be ranked as follows for large craters.

- (1) Concrete with crushed stone base.
- (2) Asphalt over crushed stone.
- (3) Continued improvements to crushed stone repairs.
- (4) Asphalt without a stone base.

b. If time is critical and no material constraints are imposed, the ranking would be:

- (1) Asphalt over crushed stone.
- (2) Continued improvements to crushed stone.
- (3) Asphalt without a stone base.
- (4) Concrete with crushed stone base.

c. If both time constraints and the shortage of both asphalt and concrete exist, then the preferred order would be:

- (1) Continued improvements to crushed stone.
- (2) Asphalt over crushed stone.
- (3) Concrete with crushed stone base.
- (4) Asphalt without a stone base.

d. As can be seen from these rankings, the unit performing crater repairs must retain the flexibility in personnel and equipment to perform various types of repairs depending on the situation that exists. The Army (through its own capabilities or by using HN resources) must take steps to ensure that concrete and asphalt are available in the quantities needed and at the locations required for repair. To a certain extent, this is true of crushed stone; however, crushed stone is more adaptable to stockpiling at the air base prior to time of need.

12. Small Crater Repair Techniques. The crushed stone, rigid pavement, and flexible pavement repair methods are acceptable for small craters. As with large craters, the methods will depend on the time constraints and material available. However, since the small crater is less than 3 feet deep, the best repair method is 24 inches of crushed stone compacted from the top with 32 passes of a 10-ton or larger vibratory roller. The FOD cover could be the emulsified asphalt and sand blotter or a silikal cap. Silikal would require more time for placement and may prove difficult to use in the rain.

13. Spall Repair Techniques. Silikal is the preferred method for spall repair. However, if silikal is not available, the second choice is hot-mix or cold-mix asphalt placed in the cavity and rolled with a steel wheeled roller. The last choice would be the use of steel plates. If time permits, type I PCC would be acceptable. Silikal does not perform well when placed under wet conditions. Therefore, some type of canopy or cover and an air compressor would be needed to dry the cavities. In inclement weather, the steel plate may be the only acceptable solution.

IV. RECOMMENDATIONS

14. Summary. Figure 4 provides a summary of the recommended repair techniques that the US Army should adopt for use during the current time frame. The recommendations are listed in order of priority for Class B and Class A repairs for large and small craters and spalls.

RECOMMENDED REPAIR TECHNIQUES IN PRIORITY RANKING

<u>Class B</u>		
<u>Method</u>	<u>Tactical</u>	<u>Nontactical</u>
Crushed stone	Preferred	Preferred
AM-2 mat	Not available	Not available
XM-19 mat	Not now usable	Second choice
<u>Class A (tactical and nontactical vary only in depth)</u>		
<u>Method</u>	<u>Ranking</u>	<u>Remarks</u>
Concrete	1	Requires more time and materials
Asphalt over stone	2	Requires asphalt plant nearby
Stone with improvement	3	Least materials and time
Asphalt	4	Difficult to use
<u>Spalls</u>		
<u>Method</u>	<u>Ranking</u>	<u>Remarks</u>
Silikal	1	Wet weather problems
Asphalt	2	Hot or cold mix
Concrete	3	Takes curing time
Steel plates	4	May need in inclement weather

Figure 4

15. Future Studies. There are a number of studies that the US Army should undertake to increase its capability for meeting its ADR mission requirements. It is recommended that these studies include the following.

a. HN resources. Collection and compilation of HN resources for quarries, asphalt production, and concrete production.

b. Collateral damage. The extent of collateral damage repair required of US Army engineer forces should be quantified in order that force structuring can be realistically accomplished by war planners.

c. End ramps and anchor systems for the XM-19 mat. Needs should be identified based on use of this mat as a patch, and action should be taken to procure the end ramps, half panels, and anchor systems required.


LAST PAGE OF MAIN PAPER

ANNEX A

TYPICAL CRATER

ANNEX A

TYPICAL CRATER




LAST PAGE OF ANNEX A

ANNEX B

CRUSHED STONE REPAIR

ANNEX B

CRUSHED STONE REPAIR




LAST PAGE OF ANNEX B

ANNEX C

GRADATION CURVES FOR CRUSHED STONE

GRADATION CURVES FOR CRUSHED STONE



ENG FORM 2087
1 MAY 63

ANNEX D

BIBLIOGRAPHY

ANNEX D

BIBLIOGRAPHY

Applied Engineering Resources, Inc., Bomb Damage Repair (BDR) Damaged Pavement Removal and Crater Backfill Equipment Study. AFCEC-TR-76-18 prepared by Edward Concha and Glen Erickson under Contract No. F29601-75-C-0052 for US Air Force Civil Engineering Center. Santa Barbara, California, December 1976 (UNCLASSIFIED).

Boeing Commercial Airplane Company, Roughness Criteria for Bomb Damage Repair of Airfield Pavements. CEEDO-TR-77-50 prepared by J. R. Kilner under Contract No. FO8635-76-C-0102 for US Air Force Civil and Environmental Engineering Development Office. Seattle, Washington, October 1977 (UNCLASSIFIED).

Davis, Walter R., "The Wartime Role of Air Force Civil Engineers," Air Force Engineering and Service Quarterly. Volume 18, No. 4. November 1977 (UNCLASSIFIED).

Department of Defense, DOD Directive 1315.6, Responsibilities for Military Troop Construction Support of the Department of Air Force Overseas. Washington, D. C., August 1978 (UNCLASSIFIED).

Department of Defense, Joint Chiefs of Staff, J-4, Joint Contingency Construction Requirements Studies II (JCCRS II) (U). 3 Volumes. Washington, D. C., November 1979 (SECRET).

Department of the Air Force, Air Force Systems Command, Air Force Civil Engineering Center, AM-2 Base Course Requirements on Debris Subgrades. AFCEC-TR-76-45 by Raymond S. Rollings. Tyndall Air Force Base, Florida, March 1977 (UNCLASSIFIED).

_____ , F-4C Have Bounce Tests. ESL-TR-79-13 by L. Caldwell, et al. Tyndall Air Force Base, Florida, March-April 1979 (UNCLASSIFIED).

_____ , Interim Field Procedure for Bomb-Damage Repair. ESL-TR-79-01 by M. McNerney. Tyndall Air Force Base, Florida, April 1979 (UNCLASSIFIED).

_____ , Interim Methods for Rapid Repair of Small Pavement Craters. Tyndall Air Force Base, Florida, March 1976 (UNCLASSIFIED).

Department of the Air Force, Air Force Systems Command, Air Force Engineering and Services Laboratory, Air Force Engineering and Services Center, Civil and Environmental Engineering Development Office, Laboratory Evaluation of Expedient Pavement Repair Materials. CEEDO-TR-78-44 by R. S. Rollings. Tyndall Air Force Base, Florida, June 1978 (UNCLASSIFIED).

_____ , Resin Concrete for Bomb Damage Repair of Airfield Pavements. CEEDO-TR-77-53 by Raymond S. Rollings. Tyndall Air Force Base, Florida, November 1977 (UNCLASSIFIED).

Department of the Air Force, Air Force Systems Command, Air Force Flight Dynamics Laboratory, Dynamic Response of an RF-4C Aircraft to a Bomb-Damage Repair Patch. AFFDL-TM-73-22-FYS by Terry M. Harris. Wright-Patterson Air Force Base, Ohio, February 1974 (UNCLASSIFIED).

Department of the Air Force, Air Force Systems Command, Air Force Institute of Technology, "Rapid Runway Repair...A Civil Engineering Mission," Air Force Civil Engineer. By Robert L. Bell. Wright-Patterson Air Force Base, Ohio, February 1975 (UNCLASSIFIED).

Department of the Air Force, Air Force Systems Command, Air Force Weapons Laboratory, Analysis of Dynamic Aircraft Responses to Bomb-Damage Repair. AFWL-TR-75-138 by Lawrence D. Hokanson. Kirtland Air Force Base, New Mexico, November 1975 (UNCLASSIFIED).

_____, Bomb-Damage Repair Analysis of a Scale Runway, Project Essex. AFCEC-TR-75-27 by Lawrence D. Hokanson and Raymond S. Rollings. Kirtland Air Force Base, New Mexico, March 1976 (UNCLASSIFIED).

_____, Comparison of the British Class 60 Trackway and AM-2 Mat for Bomb Damage Repair Application. AFWL-TR-75-149 by Raymond S. Rollings. Kirtland Air Force Base, New Mexico, November 1975 (UNCLASSIFIED).

_____, Computer Program for the Prediction of Aircraft Response to Runway Roughness. AFWL-TR-73-109, Volumes I and II by A. Gerardi and A. K. Lohwasser. Kirtland Air Force Base, New Mexico, April 1974 (UNCLASSIFIED).

_____, Effects of Small Cratering Charges on Pavements. AFWL-TR-70-66 by Raman Pichumani and James L. Dick. Kirtland Air Force Base, New Mexico, December 1970 (UNCLASSIFIED).

_____, Field Test of Standard Bomb-Damage Repair Techniques for Pavements. AFWL-TR-75-148 by Lawrence D. Hokanson. Kirtland Air Force Base, New Mexico, October 1975 (UNCLASSIFIED).

_____, Model Study of C-5A Landings on AM-2 Landing Mat. AFWL-TR-72-210 by F. W. Kiefer, et al. Kirtland Air Force Base, New Mexico, August 1973 (UNCLASSIFIED).

_____, Tyndall AFB Bomb-Damage Repair Field Test, Documentation and Analysis. AFWL-TR-74-226 by Lawrence D. Hokanson. Kirtland Air Force Base, New Mexico, October 1975 (UNCLASSIFIED).

Department of the Air Force, Air Force Systems Command, Air Force Weapons Laboratory, Civil Engineering Research Division, Dynamic In-Situ Material Property Determination. By Joseph H. Amend III. Kirtland Air Force Base, New Mexico, 1977 (UNCLASSIFIED).

Department of the Air Force, Air Force Systems Command, Air Proving Ground Center, Development Test of Rapid Runway Repair Technique for Bomb-Damaged Runways. APGC-TR-65-16 by G. E. Carroll and P. T. Sutton. Eglin Air Force Base, Florida, February 1965 (UNCLASSIFIED).

Department of the Air Force, Air Force Systems Command, Air Proving Ground Center, Runway Bomb Damage Repair Test. AFGC-TR-63-40 by Dominic F. Menza and George R. Ofn. Eglin Air Force Base, Florida, July 1963 (UNCLASSIFIED).

Department of the Air Force, Headquarters, AFR 93-2, Disaster Preparedness and Base Recovery Planning. Washington, D. C., July 1974 (UNCLASSIFIED).

_____, AFR 93-3, Air Force Civil Engineer Prime Beef Program. Washington, D. C., Date Unknown (UNCLASSIFIED).

Department of the Army, Headquarters, TM 5-336, Planning and Design for Rapid Airfield Construction in the Theater of Operations. Washington, D. C., November 1965 (UNCLASSIFIED).

_____, TM 5-337, Paving and Surfacing Operations. Washington, D. C., February 1966 (UNCLASSIFIED).

Department of the Army, United States Army Corps of Engineers, Office of the Chief of Engineers, Construction Engineering Research Laboratory, Resin Concrete for Bomb Damage Repair of Airfield Pavements. CEEDO-TR-77-53 by A. Smith for the Air Force Civil and Environmental Engineering Office. Champaign, Illinois, November 1977 (UNCLASSIFIED).

Department of the Army, United States Army Corps of Engineers, Office of the Chief of Engineers, United States Army Engineer Studies Center, Study Guidance for Air Force Support Study (U). Letter to Commander, 412th ENGCOM with one inclosure. Washington, D. C., 8 January 1979 (NATO-SECRET).

Department of the Army, United States Army Corps of Engineers, Office of the Chief of Engineers, United States Army Engineer Waterways Experiment Station, A Concept for Rapid Repair of Bomb-Damaged Runways Using Regulated-Set Cement. WES-C-75-2 by George C. Hoff. Vicksburg, Mississippi, July 1975 (UNCLASSIFIED).

_____, Airfield Damage Repair. Field Reference Document by Victor C. Barber, et al. Washington, D. C., May 1979 (UNCLASSIFIED).

_____, Evaluation of Materials for Post-Attack Pavement Repair. CEEDO-TR-78-16 by C. Rone. Vicksburg, Mississippi, September 1978 (UNCLASSIFIED).

_____, Installation of XM19 Airfield Landing Mat and Ancillary Items. Instruction Report S-69-4 by H. L. Green and D. A. Ellison. Vicksburg, Mississippi, July 1969 (UNCLASSIFIED).

_____, Observation of C-5A Operations on Landing Mat Test Facility - Dyess Air Force Base, Texas. AEWES-MISC Paper-S-72-10 by H. L. Green. Vicksburg, Mississippi, March 1972 (UNCLASSIFIED).

_____, Rapid Repair of Bomb-damaged Runways. Phase I, WES-C-72-15 by P. S. Bussone, et al. Vicksburg, Mississippi, June 1972 (UNCLASSIFIED).

Department of the Army, United States Army Corps of Engineers, Office of the Chief of Engineers, United States Army Engineer Waterways Experiment Station, Repair and Restoration of Paved Surfaces, Report 1: Bomb Damage Repair Field Trials, June 1975 - November 1976. WES C-78-2 by Charles E. Collum, et al. Vicksburg, Mississippi, March 1978 (UNCLASSIFIED).

Department of the Army, United States Army Corps of Engineers, Office of the Chief of Engineers, United States Army Engineer Waterways Experiment Station, War Damage Recovery Operations for Airfields. Draft Technical Report by George Hammitt, et al. Vicksburg, Mississippi, September 1978 (UNCLASSIFIED).

Department of the Army, United States Army, Europe and Seventh Army, 18th Engineer Brigade, 293d Engineer Battalion, Technical Report 80-1-1, Field Test of Bomb Crater Repair Utilizing The Fiell-Depth Coarse Aggregate Solution. By David M. Reed. Baumholder, Federal Republic of Germany, October 1979 (UNCLASSIFIED).

_____, Technical Report 80-1-2, Field Test of Small Bomb Crater Repair Utilizing BN 25 Readimix Concrete. By David M. Reed. Baumholder, Federal Republic of Germany, October 1979 (UNCLASSIFIED).

_____, Technical Report 80-1-3, Field Test of Small Repair Utilizing Concrete and Steel Plates. By David M. Reed. Baumholder, Federal Republic of Germany, October 1979 (UNCLASSIFIED).

_____, Technical Report 80-1-4, Field Test of Bomb Crater Repair Utilizing Crushed Stone. By David M. Reed. Baumholder, Federal Republic of Germany, October 1979 (UNCLASSIFIED).

_____, Technical Report 80-1-5, Field Test of Large Crater Repair Utilizing BN 25 Readimix Concrete. By David M. Reed. Baumholder, Federal Republic of Germany, November 1979 (UNCLASSIFIED).

Department of the Army, United States Army, Europe and Seventh Army, Headquarters, Commander in Chief and United States Air Force Europe, Commander in Chief, jointly, Wartime Airfield Damage Repair (ADR) Operations (U). Draft Memorandum of Agreement. Heidelberg, Federal Republic of Germany, February 1980 (CONFIDENTIAL).

Departments of the Army and the Air Force, jointly, TM 5-330 and AFM 86-3, Planning and Design of Roads, Airbases, and Heliports in the Theater of Operations. Volume II. Washington, D. C., September 1968 (UNCLASSIFIED).

Department of the Navy, Naval Facilities Engineering Command, Overview of Air Force Runway Bomb Damage Repair Program. Technical Manual No. M-53-78-1. Port Hueneme, California, May 1978 (UNCLASSIFIED).

Department of the Navy, Naval Facilities Engineering Command, Naval Civil Engineering Laboratory, A Structural Evaluation of Rapid Methods of Backfilling for Bomb Damage Repair. AFWL-TR-73-29 prepared by J. B. Forrest and T. A. Shugar for Department of the Air Force. Port Hueneme, California, March 1974 (UNCLASSIFIED).

Department of the Navy, Naval Facilities Engineering Command, Naval Civil Engineering Laboratory, A Structural Evaluation of Rapid Methods of Backfilling for Bomb Damage Repair. AFWL-TR-74-272 prepared by J. B. Forrest and J. Crawford under Contract No. MIPR-72-6 for the US Air Force. Port Hueneme, California, August 1975 (UNCLASSIFIED).

_____, Repair of Bomb-Damaged Runway. NCEL-TR-R-297 by T. Yoshihara. Port Hueneme, California, June 1964 (UNCLASSIFIED).

Departments of the Navy, the Army, and the Air Force, jointly, DM 21.3, TM 5-825.2, AFM 88-6, Flexible Pavement Design for Airfields. Chapter 2. Washington, D. C., August 1978 (UNCLASSIFIED).

Farnbrough, J. S., "Operation Annabelle," The Royal Engineers Journal. Volume 90, No. 2. June 1976 (UNCLASSIFIED).

Federal Republic of Germany, German Air Force, Startbahnschnellinstandsetzung. Fuerstenfeldbruck, Federal Republic of Germany, Date Unknown (UNCLASSIFIED).

Hokanson, Lawrence D., "Airfield Bomb Damaged Repair," The Military Engineer. Volume 67, No. 439. September-October 1975 (UNCLASSIFIED).

Jewsbury, F. E., "A Possible Solution to the Problem of Rapid Runway Repair," The Canadian Military Engineer. Fall 1971 (UNCLASSIFIED).

Monsanto Research Corporation, Rapid Repair of Bomb-Damage Runways. AFML-TR-66-141 prepared by B. R. Hickman, et al. under Contract No. AF 33(615)-1484 for US Air Force Materials Laboratory. Dayton, Ohio, March 1966 (UNCLASSIFIED).

North Atlantic Treaty Organization, NATO STANAG 2929--Airfield Damage Repair (U). Draft. Brussels, Belgium, 26 March 1979 (NATO-CONFIDENTIAL).

Southwest Research Institute, Bomb Crater Damage to Runways. AFWL-TR-72-183 by Peter S. Westine. San Antonio, Texas, February 1973 (UNCLASSIFIED).

_____, New Concept Study for Repair of Bomb Damaged Runways. By E. Jack Baker, et al. San Antonio, Texas, 1979 (UNCLASSIFIED).

Syracuse University Research Corporation, Rapid Runway Repair Study. AFCEC-TR-75-19 prepared by Leo L. Boyko and George G. Sawyer under Contract No. F086-75-C-0010 for US Air Force Civil Engineering Center. Syracuse, New York, August 1975 (UNCLASSIFIED).

Texas Tech University, Structural Repair of Bomb Damage to Airfield Runways. AFWL-TR-73-214 prepared by Jimmy L. Smith and William W. Morris under Contract No. F29601-72-C-0043 for US Air Force Weapons Laboratory. Lubbock, Texas, February 1974 (UNCLASSIFIED).

United States Gypsum Company, Super Strength Gypsum Cement for Rapid Runway Repair. CEC-70-003 by C. T. Lehmann, et al. Chicago, Illinois, August 1970 (UNCLASSIFIED).

University of New Mexico, Civil Engineering Research Facility, Effects of Pavement Design on Cratering Damage from Penetrating Weapon. AFWL-TR-74-197 prepared by B. Cassino and D. Chavez under contract for US Air Force Weapons Laboratory. Kirtland Air Force Base, New Mexico, October 1975 (UNCLASSIFIED).

_____, Evaluation of Liquid Binder for Airfield Bomb-Damage Repair. AFCEC-TR-75-25 prepared by John P. Nielsen and Vincent Cassino under contract for US Air Force Civil Engineering Center. Kirtland Air Force Base, New Mexico, September 1975 (UNCLASSIFIED).

University of Texas, An Investigation of the Use of Polymer-Concrete for Rapid Repair of Airfield Pavements. CEEDO-TR-78-10 prepared by M. McNerney under Contract No. F29601-74-C-0030 for the US Air Force Civil and Environmental Engineering Office. Austin, Texas, January 1978 (UNCLASSIFIED).

Van Orman, James R. and Kenneth J. Knox, "Developments in Rapid Runway Repair," The Military Engineer. Volume 71, No. 464. December 1979 (UNCLASSIFIED).

Western Company, Rapid Backfilling of Runway Craters. PREC-TR-71-1 prepared by R. M. Mueller under Contract No. F33(615)-70-C-1768 for US Air Force Civil Engineering Center. Richardson, Texas, April 1971 (UNCLASSIFIED).

_____, Rapid Repair and Construction with Fast-Fix Cements. AFWL-TR-71-42 prepared by G. D. Beal and R. W. Chandler under Contract No. F33615-68-C-1258 for US Air Force Weapons Laboratory. Richardson, Texas, October 1971 (UNCLASSIFIED).

_____, Rapid Repair of Bomb-Damaged Runways. Volume I, AFAPL-TR-67-165 prepared by W. F. Setser, et al. under Contract No. AF33(615)-3747 for US Air Force Aeronautical Propulsion Laboratory. Richardson, Texas, March 1968 (UNCLASSIFIED).

_____, Rapid Repair of Bomb-Damaged Runways. Volume II, AFAPL-TR-67-165 prepared by G. T. Pruitt, et al. under Contract No. AF33(615)-3747 for US Air Force Aeronautical Propulsion Laboratory. Richardson, Texas, April 1968 (UNCLASSIFIED).

_____, Utilization of Fast-Fix Concrete for Rapid Repair of Mortar and Rocket Damaged Runways. AFAPL-TR-68-55 prepared by R. Anderson and T. S. Ames under Contract No. 33(615)-68-C-1117 for US Air Force Aeronautical Propulsion Laboratory. Richardson, Texas, May 1968 (UNCLASSIFIED).

END

DATE
FILMED

10-81

DTIC